


## OSSP Panel Feedthrough Plug Receptacle Press-Fit Installation 1059901-1

Instruction Sheet 408-4654 (was A.P. 47-020) 08 FEB 00 Rev O EC 0990-0122-00


CONNECTOR TYPE	CABLE TYPE	TOOLS REQ'D
OSSP PANEL FEED-THROUGH PLUG RECEPTACLE PRESS-FIT INSTAL.	N/A	INSTALLATION TOOL: 2598-5212-54

CONNECTOR



## ASSEMBLY OPERATIONS

- 1.0 MOUNTING HOLE PREPARATION
  - 1.1 DRILL .034±.001 DIAMETER PILOT HOLE THRU PANEL.
  - 1.2 INSERT STEP REAMER INTO PILOT HOLE AND REAM .156±.001 DIAMETER HOLE TO DEPTH SHOWN.
  - 1.3 PLATE PER CUSTOMER APPLICATION RECOMMENDED MAXIMUM TOTAL PLATING IS .00019.
  - 1.4 CLEAN IN SOLVENT.



- 2.0 INSTALLATION OF CONNECTOR INTO PANEL
  - 2.1 PRESS CONNECTOR INTO PANEL USING INSTALLATION TOOL.

NOTE: CONNECTOR SHOULD BE BOTTOMED IN PANEL, AS SHOWN.

