Exothermically

Welded

Grounding

Connections

- REQUIRED TOOLSHandle Clamps
 - HCLAMP-3 (A Price Key Molds)
 - HCLAMP-4 (B Price Key Molds)
- Flint Ignitor -FLINT IGNITOR

SUGGESTED TOOLS

- Cable Cleaning Brush -CC-BRUSH
- Slag Removal Spade SLAG-SPADE
- Mold Cleaning Brush MC-BRUSH
- Torch Head EXO-TORCH

GENERAL INFORMATION

SH makes a straight butt splice.

HORIZONTAL SPLICE CONNECTIONS

Conductors in plane

- Molds shown are for concentric strand AWG conductors.
- Bare Class A, B, and C based on ASTM Standard Specifications
- Solid conductors are designated with a "S" suffix after the conductor
- Mold Price Key is the last letter in the Mold Catalog Number. i.e. A or B.
- For wear plates add the letter W to the end of the Mold Catalog Number

	da	
	-	
		1

SH

Cable Size	Mold Catalog Number	Weld Metal	Mold Price Key
#6 sol	SH6S-6SA	25	А
#6	SH6-6A	25	А
#4 sol	SH4S-4SA	25	А
#4	SH4-4A	25	А
#2 Sol	SH2S-2SA	32	А
#2	SH2-2A	32	А
1/0 sol	SH1/0S-1/0SA	45	А
1/0	SH1/0-1/0A	45	А
2/0	SH2/0-2/0A	65	А
3/0	SH3/0-3/0A	90	А
4/0 sol	SH4/0S-4/0SA	90	А
4/0	SH4/0-4/0A	90	А
250 MCM	SH250-250A	115	А
300 MCM	SH300-300A	115	А
350 MCM	SH350-350A	150	А
500 MCM	SH500-500A	200	А
750 MCM	SH750-750B	2 x 150	В
1000 MCM	SH1000-1000B	2 x 200	В

Contact TE Connectivity for molds with other conductor sizes and configurations.

