

OSP Panel Feedthrough Plug Receptacle Press-Fit Installation 1059651-1


Instruction Sheet 408—4600 (was A.P. 45–111) 07 FEB 00 Rev O EC 0990–0134–00

CONNECTOR TYPE	CABLE TYPE	TOOLS REQ'D	
OSP PANEL FEED- THROUGH PLUG RECEPTACLE PRESS-FIT INSTAL.	N/A	INSTALLATION TOOL: 2598-5213-54	
CONNECTOR			

CONNECTOR O'- RING CONNECTOR

ASSEMBLY OPERATIONS

- 1.0 MOUNTING HOLE PREPARATION
 - 1.1 DRILL .046±.001 DIAMETER PILOT HOLE THRU PANEL.
 - 1.2 INSERT STEP REAMER INTO PILOT HOLE AND REAM .250±.001 DIAMETER HOLE TO DEPTH SHOWN.
 - 1.3 COUNTER BORE .312 DIAMETER TO A DEPTH OF .045.
 - 1.4 PLATE PER CUSTOMER APPLICATION RECOMMENDED MAXIMUM TOTAL PLATING IS .00019.
 - 1.5 CLEAN IN SOLVENT.



- 2.0 INSTALLATION OF CONNECTOR INTO PANEL
 - 2.1 PRESS CONNECTOR INTO PANEL USING INSTALLATION TOOL.

NOTE: CONNECTOR SHOULD BE BOTTOMED IN PANEL. AS SHOWN.

