

Tyco Electronics Substance Report

DG, MANJUNATH
Dec 5, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

General Properties

Part Name	02P MTA156 HDR ASSY FL ST LF
Part Number	3-641208-2
Total Part Weight (g)	0.645193
Unit of Measure	EA (each)

REPORTED CONTENT

Name	CAS Number	Weight (g)	Weight (%)
Tin	7440-31-5	0.001345	0.208411
Arsenic	7440-38-2	0.000038	0.005924
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000003	0.000529
zinc	7440-66-6	0.107009	16.585592
Cobalt	7440-48-4	0.000382	0.059240
Mercury	7439-97-6	0.000002	0.000296
Beryllium	7440-41-7	0.000004	0.000592
Iron	7439-89-6	0.000191	0.029620
Chromium	7440-47-3	0.000004	0.000592
Lead	7439-92-1	0.000271	0.041941
Manganese	7439-96-5	0.000191	0.029620
Antimony oxide	1309-64-4	0.014234	2.206158
Gold	7440-57-5	0.001119	0.173390
Cadmium	7440-43-9	0.000038	0.005924
Antimony	7440-36-0	0.000038	0.005924
Copper	7440-50-8	0.273280	42.356276
Unspecified Compliant Substance	Unspecified Compliant Substance	0.244577	37.907560
Nickel	7440-02-0	0.002467	0.382411
All (18 items)			
Total		0.645193	