


A-MP STRAIN RELIEF CLAMP FOR SERIES "M" AND MINIATURE DUALATCH* CONNECTORS

IS 7019	
RELEASED	7-12-62
REVISED	12-9-63



- Attach Strain Relief Assembly to Connector Block using:
 - (a) 4-40 X 3/8 Fillister Head Screws with lock-washers and Nuts.

ASSEMBLY NUMBER	FOR USE ON
201846	34 Position Series "M" Connectors
	40 Circuit Miniature Dualatch Connectors

- (b) Series "M" Corner Guide Pins or Sockets for Series "M" Connectors.
- (c) Miniature Dualatch Corner Guide Pins for Miniature Dualatch Connectors.
- 2. Bundle Cable so that it will pass thru "U" Clamp .
- 3. Assemble "U" Clamp as shown.
- 4. Tighten "U" Clamp Nuts.