




Fig.1

1.はじめに

この取扱説明書はハイテンプヒーターコネクタ及びヒーターコネクタ用引抜工具 (型番 1366704-1, 1366705-1, 1366706-1) の取り扱いについて説明するものです。

ご使用前に必ずお読み下さい。

1.INTRODUCTION

This instruction sheet describes the use of the Extraction Tool for High Temp Heater Conn. and Heater Conn. (P/N 1366704-1, 1366705-1, 1366706-1).

READ THIS MANUAL CAREFULLY BEFORE OPERATION.

2.適用コネクタ

2.APPLICABLE CONNECTORS

コネクタ Connector			引抜工具 Extraction Tool	
名称 Name	端子型番 Contact P/N	ハウジング型番 Housing P/N	型番 Part No.	ハンドルの色 Handle Color
ハイテンプ ヒーター コネクタ High Temp Heater Connector	1318315-1	タイプ1,2,3 Type I, II, III	1,2,3-1318316-1	緑 Green
	1318315-2	タイプ 4 Type IV	4-1376110-1	黒 Black
ヒーターコネクタ Heater Connector	917480-2 917481-2	917482-1,917483-1 353200-1,353201-1,1123278-1	1366706-1	青 Blue

3.使用方法

以下の手順でご使用下さい。

- 1) 工具の電線逃げ溝を電線の方向にあわせ、引き抜きたい個所のハウジングランス部に挿入して下さい(Fig.2)。
- 2) 工具を端子に突き当たるまで挿入するとランスが開き、端子が抜ける状態になります(Fig.3)。
- 3) 工具を挿入した状態で電線を持ち端子を引き抜いて下さい(Fig.4)。

注記

スムーズに抜けない場合は一度工具を抜いて挿入し直して下さい。

引き抜いたコネクタを再使用する場合はコネクタに異常が無いか確認し、異常があれば使用しないで下さい。

工具を挿入するだけでコネクタのランスは解除されます。
 ランスや工具をいためますので工具でこじらないで下さい。

4.保守

- 1) 工具は使用後きれいな布で拭き乾燥した場所に保存して下さい。
- 2) 工具先端部に傷が付いていないか目視にて確認して下さい。もし傷が付いていた場合はランスを傷つけることがありますので新しい工具をご購入下さい。

3.OPERATION PROCEDURE

Extract the terminal in following procedure;

- 1) Hold the tool by hand and insert it into housing so that tip of tool touches to lance of housing (Fig.2).
- 2) Insert the tool until tool tip touches the terminal then the lance of housing is moved outside and the terminal can be extracted (Fig.3).
- 3) Keep the tool in the housing, hold the wire and pull out the terminal from housing (Fig.4).

NOTES

If the terminal cannot be pull out smoothly, extract the tool and reinsert the tool.

When reusing the extracted contact, make sure that there are no damages on the contact. If there are any damages, DO NOT reuse the contact.

Contact lance could be released by just inserting the extraction tool. DO NOT apply excess force when you push in the tool into housing. Contact lance and/or tool may be damaged.

4.MAINTENANCE

- 1) Wipe the tool with clean cloth and store in dry area.
- 2) Check the tool visually so that the tool is not damaged especially on tip of the tool. If damaged, replace the tool.




Fig.2




Fig.3




Fig.4